



# LIFTING BRACKET

**THE DESLAURIERS LIFTING BRACKET** bolts to the vertical flange using standard assemble bolts. Lifting brackets allow column formwork to be lifted and moved as a single assembled unit.

- Deslauriers' 1 ft and 2 ft forms do not have lifting eyes, thus lifting brackets are recommended
- 2000 lb capacity per bracket
- Minimum of two required per column
- 1 1/2" hole for lifting lines
- Constructed out of 1/4" steel
- Sold and rented in sets of 2

**CAT#: HDS-LB** --Sale

**CAT#: HD-LB** --Rent



# HEAVY DUTY LIFTING BRACKET

**THE DESLAURIERS HEAVY DUTY LIFTING BRACKET** bolts to the horizontal flanges using standard assemble bolts. It allows column formwork to be lifted and moved either as a single unit or as an assembled unit. Deslauriers recommends using lifting spreader bar for lifting all column forms.

- 4000 lb capacity per bracket
- Minimum of two required per column
- 1 1/2" hole for lifting lines
- Constructed out of 1/4" steel
- Sold and rented in sets of 2

**CAT#: HDS-HDLB** --Sale

**CAT#: HD-HDLB** --Rent

