


Tremmie Hopper Bracket Assembly Guide










Included Hardware

- (14) 1/4-20 Star Nut
- (8) 1/4-20 Round Head Screw
- (6) 1/4-20 Cap Screw
- (2) Tremmie Bracket Set



- Insert cap screw to base of Tremmie Hopper, secure cap screw with star. Repete this for all 3 pre-drilled holes









To attach Tremmie Bracket Set

- Line up exterior Tremmie Bracket with the pre-drlled holes on the exterior of the Tremmie Hopper. Insert (4) round head screws into pre-drilled holes for each Tremmie Bracket Set.

To securing Tremmie Bracket Set

-Place the flat bracket to the interior of the Tremmie Hopper.
Simply line up with the round head screws and secure with star nut



